

# FACILITY COMPLIANCE AUDIT REPORT

# Division of Waste Management Solid Waste Section



UNIT TY	YPE: (check all	that apply	to th	us audit v	rith s	ame Permi	t number)	
Lined MSWLF	LCID	YW		Transfer	X	Compost	SLAS	COUNTY: Yancey County
Closed MSWLF	HHW	White goods	X	Incin		T&P	FIRM	PERMIT NO.: 100-03T
CDLF	Tire T&P / Collection	Tire Monofill		Industrial Landfill		DEMO	SDTF	FILE TYPE: COMPLIANCE

Date of Audit: September 19, 2002.

Date of Last Audit: August 8, 2002. # Date Doctor
7,18,08 DIN5166

Fac/Perm/Co ID #

100-03T

FACILITY NAME AND ADDRES	FA	CIL	LITY	NAME	<b>AND</b>	<b>ADDRESS</b>
--------------------------	----	-----	------	------	------------	----------------

Yancey County Transfer Station

Booneford Rd, Bandana, NC. 28714

# FACILITY CONTACT NAME AND PHONE NUMBER:

Tom Tipton, Public Works Director 828-678-9180

### FACILITY CONTACT ADDRESS (IF DIFFERENT):

Court House, Room 13, Burnsville, NC. 28714

## **AUDIT PARTICIPANTS:**

Albert A. Hetzell WMS, Solid Waste Section, DENR Pat Williams, Transfer Station Operator, WMI

## STATUS OF PERMIT:

Active - Review Date September 7, 2005

#### **PURPOSE OF AUDIT:**

Comprehensive Audit

## NOTICE OF VIOLATION(S) (citation and explanation): None

mYou are hereby advised that, pursuant to N.C.G.S. 1304-22, an administrative penalty of up to \$5,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

### STATUS OF PAST NOTED VIOLATIONS (List all noted last audit): None

#### OTHER COMMENTS /SUGGESTIONS:

- 1.) Some of the cracks have been repaired, new cracks have appeared in the tipping floor. The steel lip on loading bay is deteriorating and has broken away from concrete floor.
- 2.) Waste water collection trench clean of debris.
- 3.) Waste stream being screened for non permitted waste.
- 4.) Overall operation OK, metal/white goods area OK.

Please contact me if you have any questions or concerns regarding this audit report.

Regional Representative/WMS

Phone: 828-251-6784 ext. 280

Mailed on : September 20, 2002 by	hand delivery	X	US Mail	Certified No. [_]	
	1			i	